

April 28, 2015

To whom it may concern:

LEADER INSTRUMENTS CORPORATION regrets to inform you that our Service Department can no longer repair our LV5700(A) and LV5750 waveform monitors. The reason is because these models were discontinued over 7 (seven) years ago from our product line.

We would like to apologize for any inconvenience this issue may cause to you and your company operations.

Sincerely,

Makoto Mizusawa

Makoto "Mike" Mizusawa
Deputy General Manager
LEADER INSTRUMENTS CORPORATION